



View from South of Seaford Road near intersection of Willis Circle and Robanna Drive, facing north.

**VISUAL ASSESSMENT  
PHOTOSIMULATION - PAGE 1**

PROJECT REVIEW  
VISUAL IMPACT ANALYSIS  
NTELOS - RMB 6204-02  
**Seaford Baptist Church**  
SEAFORD, VIRGINIA

**MSA, P.C.**

ENVIRONMENTAL SCIENCES, PLANNING,  
SURVEYING, ENGINEERING, LANDSCAPE ARCHITECTURE


5033 ROUSE DRIVE  
VIRGINIA BEACH, VIRGINIA 23462  
(757) 490 - 9264  
FAX (757) 490 - 0634



DATE:  
**6/20/2002**

SCALE:  
**N/A**

MSA JOB #:  
**97023BC**



View looking south from Clark Lane.

**VISUAL ASSESSMENT  
PHOTOSIMULATION - PAGE 3**

PROJECT REVIEW  
VISUAL IMPACT ANALYSIS  
NTELOS - RMB 6204-02  
**Seaford Baptist Church**  
SEAFORD, VIRGINIA

**MSA, P.C.**

ENVIRONMENTAL SCIENCES, PLANNING,  
SURVEYING, ENGINEERING, LANDSCAPE ARCHITECTURE

5033 ROUSE DRIVE  
VIRGINIA BEACH, VIRGINIA 23462  
(757) 490 - 9264  
FAX (757) 490 - 0634



DATE:  
**6/20/2002**

SCALE:  
**N/A**

MSA JOB #:  
**97023BC**